


Turbine Cartridge Filters Proper Yoke Rotation & Yoke Bolt Inspection



Tube sheet inspection is required for a good gasket seal.







The yoke in this picture is installed incorrectly. The sequence is wrong and therefore can cause bleed-by.



The yoke in this picture is installed correctly. See how the leg neatly covers the other two.



Filter-Doc Corporation 303 East Brooks Road Memphis, TN 38109



Turbine Cartridge Filters Inlet Clean Air Side—Rust & Corrosion



Rust and corrosion $\underline{\text{must}}$ be addressed. If it is not, manufacturer should strongly consider voiding the warranty.







Filter-Doc Corporation 303 East Brooks Road Memphis, TN 38109

Phone: 901.396.3625 Email: Robert@filter-doc.com Fax: 901.396.3627 Greg@filter-doc.com

Turbine Cartridge Filters



Clean Air Side—Miscellaneous Troubleshooting

Do Not introduce foreign objects to turbine after filtration!!



Oily Compressed Air.



Rust & Corrosion.



Water caused by roof leaks.



Door Seal.



Transition Trench.



Filter-Doc Corporation 303 East Brooks Road

Memphis, TN 38109

Phone: 901.396.3625 Email: Robert@filter-doc.com

Fax: 901.396.3627 Greg@filter-doc.com

Turbine Cartridge Filters







Problem

Misalignment of filters results in improper sealing of the gasket which causes bleed-by.



Turbine Cartridge Filters



Correcting Misalignment with Alignment Rings



Solution of Mis-Alignments

By using Filter-Doc Crop's designed Alignment Rings, the sets of filters can be correctly aligned allowing both gaskets to properly align, making an air-tight seal between filters and filter wall.

Turbine Cartridge Filters

Alignment Rings after Installation





Solution
Filters installed using Filter-Doc alignment rings.



Filter-Doc Corporation 303 East Brooks Road Memphis, TN 38109

Phone: 901.396.3625 Email: Robert@filter-doc.com Fax: 901.396.3627 Greg@filter-doc.com

Turbine Panel Filters



2-Point Hardware

Typical Braden T-Grid with 2 Point Hardware.





By Pass.

Filter-Doc Corporation 303 East Brooks Road Memphis, TN 38109

Turbine Panel Filters







Filter-Doc Corporation 303 East Brooks Road Memphis, TN 38109


Phone: 901.396.3625 Email: Robert@filter-doc.com

Fax: 901.396.3627 Greg@filter-doc.com

Turbine Panel Filters




T-Grid



Problem

With increased air flow and multiple GE modifications that are available at this time, it can result in bowing of the existing T-grid which will allows bleed-by. Reference next page for examples.





Fax: 901.396.3627 Greg@filter-doc.com

Turbine Panel Filters



Bleed-By



Problem

This is a Braden inlet with 4-point hardware and T-Grid in front of a GE 7F.05 upgrade. The framing is insufficient between the clean side stand offs. Please refer to previous page for examples T-grid.

Solution


We suggest replacing the T-Grid with vertical columns to be 2" SS 11 gauge with ½" flanges at floor and ceiling. The vertical tubing to be stabilized with 2" SS tubing from each floor level out to tubing. This mitigates the need for extensive hardware for 4-point mounting.





Turbine Panel Filters





Filter-Doc Corporation 303 East Brooks Road Memphis, TN 38109

Phone: 901.396.3625 Email: Robert@filter-doc.com

Fax: 901.396.3627 Greg@filter-doc.com

Turbine Panel Filters



Outside Mount Pre-Filter Frames



Solutions


It has always been a problem to mount a good filter in front of an expensive "Final Filter". **Solution:** Outside Mount Pre-Filter Frames. This frame holds the 4" thick pre-filter securely to the final with gaskets poured on both sides of the frame to make an air-tight fit between the pre and final filters.

Solutions

With the Filter-Doc Corp. designed Outside Mount Pre-Filter Frames, the customer can easily change pre-filters.



303 East Brooks Road Memphis, TN 38109



Air Inlet Installation & Inspection Report

Site Name: FP & L Plant Sanford

950 S. Highway 17-92

DeBary, FL 32713

Prepared by: Greg Murphree, Filter-Doc Corporation

Date of Inspection: December 2015

Designation: 5B CT Inlet Duct & Filtration Inspection

4D & 4C Inlet Inspection and Cleaning

Filter House Manufacturer: Braden

Filter Quantity: 320 New Hydrophobic Static Filters (Gore)



Executive Summary:

The air inlet filter house inspections show the filter inlets are in <u>poor</u> condition. The filter walls are in <u>fair</u> condition and inlet floor in <u>poor</u> condition. The filter T-Grid and hardware appears in <u>good</u> condition.

Unless noted, this report covers 5B, 4C and 4D. Filter house noteworthy observations are:



5B: Bleed by caused by bent T-Grid. Repaired by Filter-Doc before installation of new filters.



5B: All anchors inspected and repaired prior to installation of new Gore filters.



5B: Fogger system inspected and in fair condition.



5B: New filter installation.



5B: Downstream leaks at front and back side of silencer section flanges. Cleaned and repaired by Filter-Doc.



5B: Bleed heat/black side of silencer inspection.

Flaking paint and rust. Scraped and vacuumed per FP & L's instructions.



5B: Bellmouth inspection.

Bellmouth in fair condition with light flaking. Cleaned and wiped down by Filter-Doc.



5B: Duct screens inspected. Little to no debris, small flakes of paint.




5B: Inlet duct inspection. Duct in very good condition. No light bleed through or debris.

5B: Inlet door to fogger area. Bad gasket replaced by Filter-Doc.



Executive Summary:

The air inlet filter house inspections show that the 4C and 4D filter inlets are in <u>poor</u> condition with corrosion, rust and flaking paint. From visual inspection, each T-Grid is stressed and bowed, but appear to be in good condition.





4D: Inlet pre-filters in fair condition. Return hardware inspected and in good condition. Dirty side inlet floor dirty and rusting.



4C & 4D: Fogger system visually inspected. Looks to be in good condition.



4C & 4D: Dirty air side after inspection. Cleaned and scraped by Filter-Doc.



4C & 4D: Back side of silencer had flaking paint. Filter-Doc scraped and cleaned per FP & L.



4C & 4D: Bellmouth typical in each inlet. Dirty with minor flaking.




4C & 4D: Bellmouth flaking.



4C & 4D: Each bellmouth was cleaned and scraped by Filter-Doc per FP & L.

In summary, both 4D and 4C were in poor condition. At a later date, Filter-Doc recommends complete blasting and coating of each inlet. There is a lot of rusting and corrosion in each inlet from the hoods to the back side of the filter T-Grid. Filter-Doc also recommends replacing the ME panel in each of the inlet hoods. At the time of inspection, the T-Grid appeared to have a slight bow that needs to be repaired when new filters are installed.

Units 4C and 4D were consistent with each for the most part in regards to corrosion and overall condition.




PROHIBITED.


3


DO NOT SCALE DRAWING


2


SHEET 1 OF 1











PROPRIETARY AND CONFIDENTIAL
THE INFORMATION CONTAINED IN THIS
DRAWING IS THE SOLE PROPERTY OF
«INSERT COMPANY NAME HERE». ANY
REPRODUCTION IN PART OR AS A WHOLE
WITHOUT THE WRITTEN PERMISSION OF
«INSERT COMPANY NAME HERE» IS
PROHIBITED.

		UNLESS OTHERWISE SPECIFIED:	
		DIMENSIONS ARE IN INCHES	DRA
		TOLERANCES: FRACTIONAL ±	CHE
		ANGULAR: MACH± BEND ± TWO PLACE DECIMAL ± THREE PLACE DECIMAL ±	
		INTERPRET GEOMETRIC	Q.A
		TOLERANCING PER: MATERIAL	CO
NEXT ASSY	USED ON	FINISH	
APPLICATION		DO NOT SCALE DRAWING	
		_	

):		NAME	DATE	
	DRAWN			
	CHECKED			TITLE:
	ENG APPR.			
	MFG APPR.			
	Q.A.			
	COMMENTS:			
				SI7F

SIZE DWG. NO.

TAread nut rev c

SCALE: 1:1 WEIGHT: SHEET 1 OF 1